



# TSCM

## Magnetic drain plug

- ▶ A magnetic insert attracts and holds ferrous particles suspended or circulating in the oil, safeguarding rotating parts.
- ▶ Recommended for high-rpm machinery.


[PRINTING NOTES](#)
[PRINT](#)

TYPE	CODE	GAS	e	g	h	f	t
TSCM0G	1GSCM00A	1/8"	14	5	6	8	5
TSCM1G	1GSCM10A	1/4"	17	5	6	8	7,5
TSCM2G	1GSCM20A	3/8"	22	6	6	10	8,5
TSCM3G	1GSCM30A	1/2"	27	8	8	10	8,5
TSCM4G	1GSCM40A	3/4"	32	10	10	12	9,5
TSCM5G	1GSCM50A	1"	40	15	15	14	9,5
TSCM6G	1GSCM60A	1" 1/4	50	15	15	15	10
TSCM7G	1GSCM70A	1" 1/2	55	15	15	15	10
TSCM8G	1GSCM80A	2"	70	15	15	17	12

TYPE	CODE	MB series	e	g	h	f	t
TSCM0M	1MSCM00A	10 x 1	14	5	6	8	5
TSCM1M	1MSCM10A	12 x 1,5	17	5	6	8	6
TSCM2M	1MSCM20A	14 x 1,5	17	5	6	8	6
TSCM3M	1MSCM30A	16 x 1,5	22	6	6	10	8,5
TSCM4M	1MSCM40A	18 x 1,5	22	6	6	10	8,5
TSCM5M	1MSCM50A	20 x 1,5	24	8	8	10	7
TSCM6M	1MSCM60A	22 x 1,5	27	8	8	10	8,5
TSCM7M	1MSCM70A	24 x 2	30	10	10	12	8
TSCM8M	1MSCM80A	30 x 2	36	10	10	12	8
TSCM9M	1MSCM90A	33 x 2	40	15	15	14	8
TSCM10M	1MSCM91A	42 x 3	50	15	15	15	10
TSCM11M	1MSCM92A	48 x 3	55	15	15	15	10
TSCM12M	1MSCM93A	60 x 4	70	15	15	17	12